

**Bromley(Kent) & District Angling Society**  
Repair and renovation of banks and swims at Scarletts lake



Damp and muddy path – view 1



Damp and muddy path – view 2





Poor swims – view 1



Poor swims – view 2





Work in progress – view 1



Work in progress – view 2





Completed – view 1



Completed – view 2





Completed – view 3



Completed – view 4